Attachment F (Appendix A)

Photographic Record for Inspection Report



Proof rolling the CFA-08 Sewage Plant Drainfield (facing east)—May 21, 2002.



Placing pit run gravel on CFA-08 Drainfield (facing north)—May 22, 2002.



Placing cobble on the pit run at the CFA-08 Drainfield (facing south/southeast)—June 20, 2002.



Smoothing the pea gravel on the CFA-08 Drainfield (facing northeast)—July 11, 2002.




Placing native soil on pea gravel (facing northeast)—July 11, 2002.



Placing soil on CFA-08 Drainfield (facing north)—August 6, 2002.



Radiological surveying of trucks used in installation of CFA-08 Drainfield cover—August 6, 2002.



Water truck being used for dust suppression during CFA-08 cover installation (facing north)—July 24, 2002.

Attachment G (Appendix A)

Integrated Waste Tracking System Material and Waste Characterization Profile





1980N ; PCM- Unsuitable for Landfarm (prev WID# 3066)

Waste Stream Information

Profile Date: 27-Jul-1999

Material Profile No.: 1980N

Tronic Bate. 27 Con 1000

Profile Name: PCM- Unsuitable for Landfarm (prev WID# 3066)

Site Treatment Plan ID:

Generating Location: CFA: Central Facilities Area

Waste Type and Action: Industrial Waste: Conditional to be Disposed at INEEL Landfill

Status: Active (waste currently being generated)
Inactive (waste not currently being generated)

Cancelled (waste never generated)

Certification, Review, & Approval

Certified

Name: Karl Unterschuetz Date: 04-Aug-1999 Phone: (208) 526-4528 FAX: (208) 526-2714

E-Mail: unteko

A waste determination process for this waste stream has been performed. Characterization data was derived by approved analytical methods or process knowledge information and any data limitations have been documented. Legally and solentifically defensible gate was used for characterization whenever possible. The required data provided in this Material & Waste Characterization Profile is complete and accurate based on the analytical data or process knowledge information used for characterization.



Name: Rhonda Rohe Date: 16-Aug-1999 Phone: (208) 526-1048 FAX: (208) 526-8632 E-Mail: ROHERD A review of the Material and Waste Characterization Profile has shown that a waste determination was performed and that the required profile data is complete and accurate based on the analytical data or process knowledge information provided. The characterization data is sufficient to justify an approval or disapproval for the material or waste to be offered for disposition.



Name: L. H. Shepherd Date: 17-Aug-1999 Phone: (208) 526-8019 FAX: (208) 526-8007 E-Mail: LS4 The Material and Waste Characterization Profile characterization data meets the INEEL RRWAC (or a contracted Off-Site Vendors acceptance criteria) for the associated material or waste type and action. A regulatory based disposition is identified for the material or waste defined by this profile. Independent review was performed and comments from the review addressed. Approval to offer this material or waste for disposition is granted.

Last Profile Update and Approval



Name: L. H. Shepherd Date: 30-Sep-2002 Phone: (208) 526-8019 FAX: (208) 526-8007 E-Mail: LS4 Waste defined by this Material and Weste Characterization Profile is currently being generated. An update and approval (as defined by the original approval statement) of this profile has been performed per the annual approval requirement established in the INEEL RRWAC.

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System






_	$\overline{\mathbf{V}}$					
	Contact	Name	E-Mail ID	Phone	Pager	Mail Stop
2.	Generator Contact	M. Russell Leavitt	leavmr@inel.gov		9376	4142
3.	Technical Contact	Sydney Flood	FLOOSW@inel.	gov (208) 526-7194	4049	4142
	Charge Number: D39207W0	3S				
4.	Material or waste type and a	ction: Industrial Waste: Condition	al to be Disposed at IN	IEEL Landfill		11818
5.	Profile Name: PCM- Unsuital	ble for Landfarm (prev WID# 3066	3)			
5 .	Waste Generated From: Routine Operations ✓ Cleanup/Stabilization Add	Cleanup/Stab. waste?	Cleanup/Stablization A	Generating State One time on On-going	ly there	ates whether s will be one ment or a s sipments
7.	Generating process descripti	ion: Cleanup material from petrole	eum (non-gasoline) sp	ills; non-hazardous conditi	onal industrial was	te.
•	3	Spill clean up of Non-Hazard boom, Pads, Socks, syntheti debris, large rocks, large wo UNSUITABLE FOR LAND FA	ic materials, Diatomaco od parts, concrete and	eousearth paper rags or o	other clean up mate	rials and/or
В.	Physical state at 70 degrees	F (solid, liquid, sludge, gel, etc.):	solid			
₽.	Yes No Does the	material contain free liquids?				
10.	Yes No Current w	aste minimization plan? (INEEL G	enerators Only)			
	Reference	: INEEL P2 Plan DOE/ID-10333(0	00)			
11.	Indicate all that apply:					
	CERCLA	Nonfriable asbestos Com	pressed gas cylinders	Wastewater	Debris - 435	5.1
	Scrap Metal	FIFRA Friab	ole asbestos	Classified material	Debris - Nor	RCRA/435.1
	OSHA carcinogen	Unused material Soil		Accountable nuclear mate	erial 🗌 RR Nonradio	pactive Metals
	PCB >= 50 ppm	Jsed oil Debr	ris - RCRA	> 100 PPM VOCs	[IW Condition	nal INSEL Landfil
	Etiologic Agent	Aerosol cans Spill	cleanup	Universal Waste	☐ IW Noncond	titional INEEL Las
					W Off-site D	Disposal

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System



25-Oct-2002

Integrated Waste Tracking System Material and Waste Characterization Profile **INFORMATION ONLY**



Page 3

1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

12.	г	Yes √ No	Is this DOT regulate	ed hazardous material? If	yes, identify DC	T primary hazar	rd:	
			Ť			sidiary hazard(s		
13.		Yes 🔽 No	At the point of gene as a treatment resid	ration did this material cor dual (i.e., ash, leachate, sp	ntain RCRA "F",	"K", "U", or "P"	isted waste ei	ther in pure form, as a mixture, or s, give applicable EPA;
	Sc	ource Code:	:					
	Fo	orm Code:	:					
			ous Waste Numbers	(40 CFR 261): and certification (40 CFR	261)			
14.		• • • • • • • • • • • • • • • • • • • •	waste determination			Process knowle	ege and/or f	↑ Both
15.		Yes [√] No		Profile contain Lab Packs?			- and -	
16.	-	Yes [7] No		Hazardous Constituent (L		tion proformad?		
10.	16	التقاال		mazaidous Constituent (c	oric) determina	non preionnes?		
17.	7	Yes No		nentation submitted? If ye 3066 file and attaceh info		ng specific spills	(process knov	vlege, data).
18.		Yes 📝 No	The following data, ICDF): Mean, Stand	by parameter, has been plant Deviation, Confidence	rovided along w e Level.	ith analytical dat	a (required for	waste to be dispositioned at the
19.	✓] Yes □ No	Is the material LDR	Compliant?				
	_			•				
20.		Yes 🔽 No	Additional narrative	:				
				Characteri	stics of M	aterial		
1.	Phy	sical Character	istics of Material					
	a.	Layer characte	eristics:					
			Layer No.	Physical State at 70 degrees F	Rang	e of Percentage of Total	1	Description (as required by GI)
			1.	solid	100 - 1	to	vol%	
	b.	Density of mat	,	or hazardous waste and re-	cyclable materia	ı).		
		Liquid:	to g/r	nl Solid:	to	_		
	c.	Yes 🗸 N	No Is this aqueous	? If yes, give total solids r	range:			
				to g/ml				
	d.	☐ Yes [☑] N	No is this incinerat	ele liquid? If yes, give visc	osity range:			
				to SSU				
2.	Che	mical Characte	ristics of Material:	_ " ***				
	a.	Does the mate	urial contain any of th	us following? For each iter	n checked ves	must include co	rreenandina a	antitative information in 2b.
	a.	DOES THE HISTO	anar contain any or tr	e tollowing r to reach itel	ii ciieckeu yes,	must molude co	nesponding di	MILITARIA DI MINISTRALIOIT III 20.
	Yes	No	- Ornanic hazad		Yes	No		
		_	- Organic based - Aqueous based		For fi	uid to be proce Oil and grea	ss in the PW se >= 10 mg/L	ΓU only

138

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

Yes	No		Yes	No	
7		Absorbents		-	
ביו	L	Response: Used in PCM clean up activaty (Rags, floor dry	For	•	waste only
Γ'n	$[\checkmark]$	Chelating agents		✓	Halogenated organic compounds >≈ 1000 mg/L as listed in 40 CFR 268, Appendix III
금	7	Aqueous liquid with reactive cyanide >= 250 ppm		7	Nickel and/or its compounds (as Ni) >= 134 mg/L
		Aqueous liquid with reactive sulfide >= 500 ppm		abla	Thallium and/or its compounds (as TI) >= 103 mg/L
\vdash	_	Air reactives			
님	2	Water reactives	For:	pilos	waste only
	$\overline{\mathbf{Y}}$		Г٦	?	Ralogenated organic compounds >= 1000 mg/L as listed in 40 CFR
\Box	$\overline{\mathbf{x}}$	Other reactives			268, Appendix III
[_]	\checkmark	Furning acids or acid gases	For	need	oil only
	\checkmark	Shock sensitive constituents		√	Arsenic >= 5 ppm
\Box	$ \mathbf{V} $	Explosives	\vdash		Cadmium >= 2 ppm
	$\overline{\mathbf{Y}}$	Pyrophorics		$\overline{\mathbf{Z}}$	• •
V	$\overline{\Box}$	Petroleum products		$\overline{\mathbf{Z}}$	Chromium >= 10 ppm
	_	Response: Diesel Fuil, and/or Motor Oll, and/or Hydrolic Fluid	Ш	✓	Lead >= 100 ppm
П	7	Oxidizers	}	\checkmark	PCBs >= 2 ppm
$\overline{\Box}$	7	Benzene		\checkmark	Total halogens >= 1,000 ppm
$\overline{\Box}$	7	PCBs >= 25 ppm		\checkmark	Total halogens >= 4,000 ppm
	Შ.	PCBs >= 5 ppm			
\Box	ď	PCB liquids	Incir	nerab	le wastes only
		PCB capacitors/ballasts			Bromine in any form
	_	PCB transformers/regulators	ΓÌ	(<u>v</u>)	Chlorine in any form
	3	•	Ō	<u> </u>	Fluorine in any form
\Box	?	PCB liquid contaminated debris or derived from a split of PCB liquid	ΪÍ	Ā	lodine in any form
1	$\overline{\mathbf{Y}}$	PCBs >= 50 ppm		7	PCBs >= 2 ppm
				_	Sulfur in any form
			\Box	<	Culor in any local

2. Chemical Characteristics of Material (continued)

b. Composition of material:

Related Characteristic	at Albertaile of Chamical	Caminana	Com	osition Rai	nge
(*Other* Where NA)	Name of Material or Chemical	Carcinogen	From	То	Units
Other	Soil, gravet, large rocks, wood parts and other rubble-like material.	Yes 🗸 No	40	90	vol%
Absorbents	Floor Dry or other synthetic material used in PCM clean up.	Yes 🗸 No	40	5	vol%
Paper and/or cloth	Rags, towels used in clean up.	☐ Yes 🗹 No	10	4	val%
Petroleum products	Diesel Fuel and/or Motor Oil, and/or Hydraulic Fluid	Yes No	10	1	vol%

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

	Flash point is:	to	Method	used:			
	(Specify Other):						
d.	Information for incinerable w	raste only:					
	(1) Heat of combustion	to	B1	ΓU/lb (2)	Ash content	to _	wt%
	(3) Total halogen content	to	• рр	ım (4)	Water content	to	wt%
	(5) Suspended particulates	content	to	mqq			_
	Metal	Known or Expected?	Exper Composition	cted on Range	Representative Sample Analysis	Datection Limit	Units
	Antimony (Sb)	☐ Yes 🔽 No	to	·	to		
	Arsenic (As)	─ Yes 🗸 No	to		to		
	Barium (Ba)	Yes 🗸 No	to		to		
	Beryllium (Be)	Yes 🗸 No	to		to		
	Cadmium (Cd)	☐ Yes 🗸 No	to		to		
	Chromium (Cr)	Yes 📝 No	to		to		
	Cobalt (Co)	Yes 🗸 No	to		to		
	Copper (Cu)	Yes 🗸 No	to		to		
	Iron (Fe)	Yes 7 No	to	·	to		
	Lead (Pb)	Yes V No	to	·	to		
	Manganese (Mn)	Yes 🗸 No	to	·	to		
	Mercury (Hg)	Yes Vo	to	·	to		
	Molybdenum (Mo)	Yes Vo	to	·	to		
	Nickel (Ni)	Yes 🗸 No	to	·	to		
	Potassium (K)	Yes 🗸 No	to	·	to		
	Selenium (Se)	Yes 📝 No	to	·	to		
	Silver (Ag)	Yes V No	to	·	to		
	Sodium (Na)	Yes V No	to		to		
	Thallium (TI)	Yes V No	to		to		
	Vanadium (V)	Yes 🗸 No	to		to		
	Zinc (Zn)	∏ Yes 🗸 No	to	•	to		

Report[MaterialProfile], Integrated Waste Tracking System





1980N ; PCM- Unsuitable for Landfarm (prev WID# 3066)

Motals	ntration Range Representative Sample Detect Limit To Units From To Units Limit Un
Metals:	TO SING TIOM TO SING CAME OF
D004	
Doos	
D006 Cadmium	<u> </u>
Decoration	
D008 Lead ✓ - D009 Mercury ✓ - D010 Selenium ✓ - D011 Silver ✓ - Volatiles: D018 Benzene ✓ - D019 Carbon tetrachloride ✓ - D021 Chlorobenzene ✓ - D022 Chloroform ✓ - D027 p-Dichlorobenzene ✓ - 1,4-Dichlorobenzene ✓ - D028 1,2-Dichlorobenzene ✓ - D029 1,1-Dichloroethylene ✓ - D035 Methyl ethyl ketone ✓ - D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Semi-Volatiles: - - - D024 m-Cresol ✓ -	
D009 Mercury ✓ - D010 Selenium ✓ - D011 Silver ✓ - Volatiles: D018 Benzene ✓ - D019 Carbon tetrachloride ✓ - D021 Chlorobenzene ✓ - D022 Chloroform ✓ - D022 Chlorobenzene ✓ - D023 1,4-Dichlorobenzene ✓ - D024 1,2-Dichlorobenzene ✓ - D029 1,1-Dichloroethylene ✓ - D035 Methyl ethyl ketone ✓ - D038 Pyridine ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Seml-Volatiles: - - D024 m-Cresol ✓ - D025 p-Cresol ✓ -	
D010 Selenium	-
D011 Silver ✓ - Volatiles: D018 Benzene ✓ - D019 Carbon tetrachloride ✓ - - D021 Chlorobenzene ✓ - - D022 Chloroform ✓ - - D027 p-Dichlorobenzene ✓ - - D028 1,2-Dichlorobenzene ✓ - - D029 1,1-Dichloroethylene ✓ - - D035 Methyl ethyl ketone ✓ - - D038 Pyridine ✓ - - D039 Tetrachloroethylene ✓ - - D040 Trichloroethylene ✓ - - D043 Vinyl chloride ✓ - - SemI-Volatiles: - - - - D024 m-Cresol ✓ - - D025 p-Cresol ✓ - <	
Volatiles: D018 Benzene ✓ - D019 Carbon tetrachloride ✓ - D021 Chlorobenzene ✓ - D022 Chloroform ✓ - D027 p-Dichlorobenzene ✓ - D028 1,2-Dichlorobenzene) ✓ - D029 1,1-Dichloroethylene ✓ - D035 Methyl ethyl ketone ✓ - D038 Pyridine ✓ - D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - SemI-Volatiles: D024 m-Cresol ✓ - D024 m-Cresol ✓ - D025 p-Cresol ✓ - D030 2,4-Dinărotoluene ✓ -	-
D019 Carbon tetrachloride	
D019 Carbon tetrachloride ✓ - D021 Chlorobenzene ✓ - D022 Chloroform ✓ - D027 p-Dichlorobenzene ✓ - L1-Dichloroethane ✓ - D028 1,2-Dichloroethylene ✓ - D039 1,1-Dichloroethylene ✓ - D038 Pyridine ✓ - D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Seml-Volatiles: D023 o-Cresol ✓ - D024 m-Cresol ✓ - D025 p-Cresol ✓ - D026 Cresol ✓ - D030 2,4-Dinărotoluene ✓ -	-
D022 Chloroform ☑ - D027 p-Dichlorobenzene ✓ - L4-Dichlorobenzene) ✓ - D028 1,2-Dichloroethane ✓ - D029 1,1-Dichloroethylene ✓ - D035 Methyl ethyl ketone ✓ - D038 Pyridine ✓ - D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Seml-Volatiles: D023 o-Cresol ✓ - D024 m-Cresol ✓ - D025 p-Cresol ✓ - D026 Cresol ✓ - D030 2,4-Dinitrotoluene ✓ -	•
D022 Chloroform D027 p-Dichlorobenzene (1.4-Dichlorobenzene) D028 1,2-Dichloroethane D029 1,1-Dichloroethylene D035 Methyl ethyl ketone D038 Pyridine D039 Tetrachloroethylene D040 Trichloroethylene D043 Vinyl chloride SemI-Volatiles: D023 o-Cresol D024 m-Cresol D025 p-Cresol D026 Cresol D030 2,4-Dinâtrotoluene	
D027 p-Dichlorobenzene (1.4-Dichlorobenzene) ✓ - D028 1.2-Dichloroethane ✓ - D029 1.1-Dichloroethylene ✓ - D035 Methyl ethyl ketone ✓ - D038 Pyridine ✓ - D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Seml-Volatiles: D023 o-Cresol ✓ - D024 m-Cresol ✓ - - D025 p-Cresol ✓ - - D026 Cresol ✓ - - D030 2,4-Dinâtrotoluene ✓ - -	-
D028 1,2-Dichloroethane ✓ - D029 1,1-Dichloroethylene ✓ - D035 Methyl ethyl ketone ✓ - D038 Pyridine ✓ - D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Seml-Volatilee: D023 o-Cresol ✓ - D024 m-Cresol ✓ - D025 p-Cresol ✓ - D026 Cresol ✓ - D030 2,4-Dinkrotoluene ✓ -	
D029 1,1-Dichloroethylene ✓ - D035 Methyl ethyl ketone ✓ - D038 Pyridine ✓ - D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Semi-Volatiles: D023 o-Cresol ✓ - D024 m-Cresol ✓ - D025 p-Cresol ✓ - D026 Cresol ✓ - D030 2,4-Dinkrotoluene ✓ -	
D035 Methyl ethyl ketone	
D038 Pyridine	
D039 Tetrachloroethylene ✓ - D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Seml-Volatiles: D023 o-Cresol ✓ - D024 m-Cresol ✓ - - D025 p-Cresol ✓ - - D026 Cresol ✓ - - D030 2,4-Dinátrofoluene ✓ - -	
D040 Trichloroethylene ✓ - D043 Vinyl chloride ✓ - Semi-Volatiles: — - D023 o-Cresol ✓ - D024 m-Cresol ✓ - D025 p-Cresol ✓ - D026 Cresol ✓ - D030 2,4-Dinárofoluene ✓ -	
D043 Vinyl chloride	<u> </u>
Semi-Volatiles: D023 o-Cresol ✓ - D024 m-Cresol ✓ - D025 p-Cresol ✓ - D026 Cresol ✓ - D030 2,4-Dinkrotoluene ✓ -	<u> </u>
D023 o-Cresol ☑ - D024 m-Cresol ☑ - D025 p-Cresol ☑ - D026 Cresol ☑ - D030 2,4-Dinktrotoluene ☑ -	
D024 m-Cresol □ - D025 p-Cresol □ - D026 Cresol □ - D030 2,4-Dinkrotoluene □ ✓	•
D025 p-Cresol □ □ - D026 Cresol □ - - D030 2,4-Dinktrotoluene □ ✓ -	
D026 Cresol	
D030 2,4-Dinitrotoluene	•
<u> </u>	
D032 Hexachlorobenzene	<u> </u>
D033 Hexachlorobutadiene	

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

EPA	Hazardous	Exp.? (Y,N)	Values	TCLP Values Type	Waste Concentration Range		Representative Sample			Detect Limit		
Code	Constituent	(1,14)	Values	Type	From	To	Units	From	To	Units	Limit	Unit
Semi-Vo	olatiles:											
D036	Nitrobenzene								·	-		
D037	Pentachlorophenol						_			_		
D041	2,4,5-Trichtorophenol						_			_		
D042	2,4,6-Trichloropheno!						_			_		
Pesticid	les and Herbicides:											
D012	Endrin						_		-			
D012	Endrin, Endrin aldehyde									_		
D013	Lindane, alpha-BHC						_			_		
D013	Lindane, beta-BHC				:		_			_		
D013	Lindane, delta-BHC				:		_					
D013	Lindane, gamma-BHC (Lindane)				:		_		•			_
D014	Methaxychlar						_		•	_		
D015	Toxaphene						_		•	_		
DC16	2,4-0						-			_		_
D017	2,4,5-TP (Silvex)				·		_					_
D020	Chlordane						_		·	-		_
D031	Heptachlor						_			_		
D031	Heptachlor epoxide						_		•	_		_
Note: "1	Type [™] column designates type of ana	alysis. (1=	Approved	Methods	, 2=Process Kr	owledge,	3=Both)					
KÇRA	Hazardous Constituents (Other))										
Underk	ying Hazardous Constituents											
	, 											

Report[MaterialProfile], Integrated Waste Tracking System

Page 7

1. Analyte Data





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

3.	Radiological C	Characteristics of Material:	
	a. Yes	No Is fissile material p	
	b. Total trans	suranic activity per gram of w	vaste is:
	c. Isotope in	ventory;	
	d. Expecte	ed radiation dose rate at surfa	ace: to mrem/hr
		at 1-m	neter: to mrem/hr
	e. 🔲 Yes	No Is the waste grea	ater than Class C as defined in 10 CFR 61.557?
	f. Content	Codes:	
			Comments
Insei	t Info	Comments	
	/2000		for NON-LANDFARM PCM MATERIAL ONLY. "Waste Stream may also consist of unleaded leanups involving absorbants. LHS 11/15/99"
06/22 Mess	/2000 arosJ /2001	gasoline small spill c	
Mess	arosJ	gasoline small spill c This profile does not spills are managed a	cover gasoline spill cleanup material that has not been analyzed for benzene. All other gasoline
06/22 Mess 10/03	arosJ	gasoline small spill o This profile does not spills are managed a	cover gasoline spill cleanup material that has not been analyzed for benzene. All other gasoline is hazardous waste under material profile 2680N.
06/22 Mess 10/03	arosJ /2001 Profile Chango	gasoline small spill o This profile does not spills are managed a	cover gasoline spili cleanup material that has not been analyzed for benzene. All other gasoline is hazardous waste under material profile 2580N. Supplemental Information Explanation Update #30: Unlock for Review & Approval for Landfill Disposal of PCM generated from 10/14/02, approx. 10 gals. Hydraulic Fluid release to soil from Road Grader @ CFA-617 Old Laundry Facility demolition project. Copy of the SNT's Spili Summary report will be placed in 1
06/22 Mess	arosJ /2001 Profile Change User Name	gasoline small spill o This profile does not spills are managed a spill	cover gasoline spili cleanup material that has not been analyzed for benzene. All other gasoline is hazardous waste under material profile 2680N. Supplemental Information Explanation Update #30: Unlock for Review & Approval for Landfill Disposal of PCM generated from 10/14/02, approx. 10 gals. Hydraulic Fluid release to soil from Road Grader @ CFA-617 Old

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System




Integrated Waste Tracking System Material and Waste Characterization Profile INFORMATION ONLY 1980N: PCM- Unsuitable for Landfarm (prev WID# 3066)



User Name	Date	Explanation
ShepherdL	02-Oct-2002 10:30 AM	SHEPHERDL. WGS. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	30-Sep-2002 04:47 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, WGS, Call Point-7; Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	30-Sep-2002 04:47 PM	Continuation of Update#28 approvals; PCM drums from ICDF; 20) 6/27/02, <50 ml. greas dripped to soil from heavy equipment; 21) 6/26/02, <50 ml. engine of spill to soil from a penting it straight of spill for soil from a Bentonite Storage Vessel engine.
		8/18/02, approx. 50 ml. diesel fuel/hyd.fluid leak to soil from roller; 24) 6/17/02, approx.50 diesel fuel spill to soil from Bomag roller/compactor; 25) 6/13/02, approx. 100 ml. engine oil/diesel fuel spill to soil from Miskin scraper; 26) 6/00/2, approx. 120 ml. diesel fuel spill from overfilling Ingersol-Rand Roller; 27) 5/29/02, <50 ml. engine oil spill to soil from "Guj 28) 5/28/02, approx. 200 ml. hyd.fluid spill to soil/bentonite from tractor-tiller; 29) 5/01/02, approx. 1 pint hyd.fluid leaked from an equipment hose to soil. Copies of SNT's Spill Summary Reports attached to file.
ShepherdL	30-Sep-2002 04:30 PM	SHEPHERDL. WGS. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	30-Sep-2002 04:29 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, WGS, Call Point-7, Authorized on Generating Unit (*CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	30-Sep-2002 04:29 PM	Continuation of Update #28: PCM drums from ICDF construction activities: 7) 9/11/02, ap 600 ml. oil spill to soil from forklift; 8) 9/10/02, approx. 500 ml. hyd.fluid spill to soil from cAT 615 Scraper on the evaporation ponds north embankment; 8/15/02, 200 ml. hyd.fluid spill to soil from hyd. jack; 12) 8/08/02, approx. 50 ml. motor oil soil from diesel generator used for pumping irrigation water; 13) 7/31/02, < 50 ml. of oil sr soil (origin unknown); 14) 7/23/02, < 100 ml.oil leak to soil from logersol-Rand engine; 15) 7/18/02, approx.100 ml. hyd.fluid spill to soil from failed O-ring on 5000 gal. water truck; 17) 7/09/02, approx.4 ml. hyd.fluid leak to soil from loose fitting on backhoe; 18) 7/8/02, <50 ml. grease spill to s front-end loader;
ShepherdL	30-Sep-2002 04:09 PM	SHEPHERDL. WGS, Call Point-4, Authorized on Generating Unit (CFA).
ShepherdL	30-Sep-2002 04:09 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL. WGS. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	30-Sep-2002 04:08 PM	Update #28: Unlock for Review & Approval for Landfill disposal of several drum quantities PCM from the following spill cleanups: 8 drums PCM from 7/10/02, 1-3 gradues; 13 drums refueling truck to soil near CFA Sewage Treatment Plant Drain Field activities; 13 drums
		from Drilling Project near ICDF & CFA facilities & ongoing ICDF construction activities intended the following releases: 1) 9/18/02, approx. 1 pint Hydraulic oil spill from drill rig to soil outs ICDF fenced area near S.W.comer; 2) 9/5/02, <1 pint hyd.fluid spill to soil from broken fit drill rig; 3) 8/22/02, approx. 1 pint diesel fuel spill to soil from re-fueling operation @ICDF laydown area; 4) 8/08/02, 15b ml. diesel fuel spill to soil from refueling truck@ICDF drillin project; 5) 8/07/02, 1/2 pint antifreeze spill to soil from vehicle along gravel road on south
		CDF; 6) 7/29/02, approx. 1 cup hyd.fluid spill to soil from drill rig@ICDF; (CONTINUED)

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System



Integrated Waste Tracking System **Material and Waste Characterization Profile** INFORMATION ONLY 1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)



В.	Drofile	Change	History

User Name	Date	Explanation
messarosj	30-Sep-2002 11:56 AM	activate profile
MessarosJ	30-Sep-2002 11:48 AM	MESSAROSJ. WGS. Call Point-4. Authorized on Generating Unit (CFA).
LeavittM	23-Jul-2002 07:58 AM	I will activate this profile for one shipment.
LeavittM	23-Jul-2002 07:52 AM	LEAVITTM. WGS. Call Point-4. Authorized on Generating Unit (CFA).
LeavittM	16-Jul-2002 07:42 AM	LEAVITTM. WGS, Call Point-4. Authorized on Generating Unit (CFA),
LeavittM	11-Jul-2002 07:31 AM	I will reactivate this profile.
LeavittM	11-Jul-2002 07:26 AM	LEAVITTM, WGS. Call Point-4, Authorized on Generating Unit (CFA).
messarosj	01-Jul-2002 01:44 PM	inactivate profile-conditional waste has been removed from RRWAC, all CFA industrial waste is now under 3332N
MessarosJ	01-Jul-2002 01:41 PM	MESSAROSJ, WGS, Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	30-May-2002 02:22 PM	Continuation of Update #27: Unlock to add 3 X 5 gal. paint cans half full of PCM from Ovard Construction spill cleanups @ HPIL area of CFA from 2 separate spills to soil: 1) 5/30/02, small motor oil spill to soil, 3 small spill fast week of Hydraulic fluid to soil, 3NT's Spill Summary Reports attached to file.
ShepherdL	30-May-2002 02:09 PM	SHEPHERDL. WGS. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	30-May-2002 01:42 PM	Update #27: Unlock for Review & Approval for Landfill Disposal; 1 X 55 gal.drum PCM from numerous spill cleanups from following ICDF area spills; 1) 5/1/02, approx. 1 pint Hydraulic fluid leak from a hose to soil; 2) 5/7/02, approx. 50 mts. Hydraulic fluid leak to soil while refilling tractor oil reservoir in high wind conditions; 3) 5/13/02, approx. 100 mts. of grease spilled to soil from Miskin tractor; 4) 5/15/02, approx. 150 mt. oil leak to ground from water truck; 5) 5/20/02; approx. 150 mt. notor oil leak to soil from Miskin tractor; 6) 5/28/02, approx. 200 mt. Hydraulic fluid spill to soil/bentonite from subcontractor tractor tiller; 7) 5/29/02, < 50 mt. engine oil spill to soil from subcontractor stationary "Guppy" equipment; add mark in Char. Req. screen question regarding LDR compliance.
ShepherdL	30-May-2002 01:37 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL. WGS. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
Shepherdi	30-May-2002 01:11 PM	SHEPHERDL. WGS. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	18-Mar-2002 02:01 PM	Update #26: Unlock for Review & Approval for Landfill Disposal; PCM from mid-January spill cleanup w/absorbants of approx. 2 gal. tube oil to asphalt from oil dispenser at the pumps (BCFA-696, change change number, Doc. of Annual Waste Stream Review & Recertification form submitted & placed in file.
ShepherdL	18-Mar-2002 01:57 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
- Applicate	7.5 (3)(01-2002 01:07 F M)	SHEPHERDL, WGS, Call Point-7, Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	18-Mar-2002 01:50 PM	SHEPHERDL WGS. Call Point-4. Authorized on Generating Unit (CFA).

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

-	e History:	
User Name	Date	Explanation
ShepherdL	13-Nov-2001 10:28 AM	Update # 25:Unlock for Review & Approval for Landfill Disposal; 1 X 55 gal.drum PCM fronumerous spills outsied INTEC fence involving WAG-3 ICDF project from: 1) 11/5/01 app 200 ml/s. hyd.fluid spill to soil from hyd.fines on subcontractor's scraper; 2) 10/29/01, app
		300 mils. hyd fluid spill to soil from hyd lines on subcontractor's scraper; 3) 10/24/01, applier hyd fluid spill to soil from hyd lines on subcontractor's scraper; 3) 10/24/01, applier hyd fluid spill to soil subcontractor's tractor pulling scraper; 4) 10/15/01, approx. 50 mils. diesel fluid spill to soil subcontractor's heavy equipment; 5) 10/8/01, (2 spills),150 mils. petroleum product leak fi subcontractor's roadgrader & 50 mils.hyd.fluid spill from a bobcat. Copy of SNT's Spill Su Reports attached.
ShepherdL	13-Nov-2001 10:14 AM	SHEPHERDL, WGS. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	06-Nov-2001 02:56 PM	Update #24: Unlock for Review & Approval for Landfill Disposal; PCM in dump truck from 11/5/01 hydraulic fluid spill cleanup from sanding truck to asphalt and soil near Nevada Si Miami Ave.(between CFA-886 &CFA-880. Copy of SNT's Spill Summary Report attached
ShepherdL	06-Nov-2001 02:51 PM	SHEPHERDL. WGS. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	04-Oct-2001 10:30 AM	Update #23: Unlock for Review & Approval for Landfill Disposal; approx. 2 drums PCM fronumerous spills outside INTEC fence involving WAG-3 ICDF project from: 1) 10/3/01, app 50 mfs. hyd-fluid spill to soil from ram arm of subcombactor's scraper; 2) 10/2/01, 1 qt. hy
		spill to soil from subcontractor's trackhoe; 3), 10/1/01, 400 mt's, hyd.fluid spill to soil from subcontractor's hyd.lines on scraper, 4), 9/19/01, 250 mt's, hyd.fluid release to soil from equipment parking area; 5) 9/18/01, 1 qt. antifreeze release to soil from a compactor; 6), 1/2 gal, hyd. fluid release to soil from subcontractor's hyd.line on scraper. Copies of E-manotifications from SNT placed in file.
ShepherdL	04-Oct-2001 10:13 AM	SHEPHERDL. WGS. Call Point-4. Authorized on Generating Unit (CFA).
MessarosJ	03-Oct-2001 12:23 PM	add comments
MessarosJ	03-Oct-2001 12:22 PM	MESSAROSJ. WGS. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	21-Aug-2001 11:07 AM	Update #22: Unlock for Review & Approval for Landfill disposal; 2 drums PCM from nume spills outside INTEC fence involving WAG-3 ICDF project from: 1} 8/15/01, 1 qt. hyd. fluid
		spills outside INTEC fence involving WAG-3 ICDF project from: 1) 8/15/01, 1 qt. hyd. fluid release to soif from bad hose fitting on tractor, 2) 8/10/1, 1 pint hyd fluid release to soif from screaper owned by subcontractor; 3) 7/30/01, 4 oz. hyd. fluid release to soil from subcontractor tractor. Existing WD file; Spill Summary Reports from Spill Notification Team (SNT) are attached.
ShepherdL	21-Aug-2001 10:54 AM	SHEPHERDL, wgs. Call Point-4, Authorized on Generating Unit (CFA).
ShepherdL	17-Jul-2001 08:46 AM	CONTINUATION UPDATE#21:Approval for Landfill Disposal; >20 bags PCM from numer spills; 9) 7/10/01, 2 to 3 gals. hyd. fluid leak from front-end loader to soil near percolation at south end of INTEC.
ShepherdL	17-Jul-2001 08:41 AM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	17-Jul-2001 08:40 AM	Update #21: Unlock for Review & Approval for Landfill Disposal; >20 bags PCM from num spill cleanups from: 1)6/5/01, 1qt.hyd.fluid release from Genie Boom to asphalt@CFA-62
		6/14/01; 2 to 5 gal.hyd.fluid spiif assoc.whire replacement on a track-mounted excavator- pan in the turret 8 rains/heavy winds displaced to soll near CFA-696(was not reported til 6/18/01); 3) 6/20/01, 1/2 cup hyd.fluid leak from front-end loader to asphalt behind CFA-6 6/21/01; 1 pint engine oil leak from steam roller to asphalt near CFA-664; 5) 6/22/01, 5 ga Propylene glycol(antifreeze) leak from bus to asphalt near CFA-696; 6) 6/25/01, 2 gal hyd.fluid leak from replaced line on piece of equipment to soil behind weld shop @staging in CFA; 7) 6/27/01, 2 to 3 gal. propylene glycol(antifreeze) leak from gov.vehicle to soil as street(south) from CFA cafeteria; 3) 7/5/01, 3 gal.hyd.fluid spill from ram on excavator to so on northwest side of CFA-696;
ShepherdL	17-Jul-2001 08:12 AM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA)
Leavitt M	16-Jul-2001 02:40 PM	update #21:

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

User Name	Date	Explanation
LeavittM	16-Jul-2001 02:09 PM	LEAVITTM. wgs. Call Point-4. Authorized on Generating Unit (CFA).
Shepherdl.	04-Jun-2001 02:36 PM	Update #20: Unlock for Review & Approval for Landfill Disposal; several plastic bags of PCM from numerous spill cleanups from: 1) 4/23/01, 1 qt. diesel fuel release to pavement @CFA-69 foeling station, 2) 4/24/01, 1 cup hydraulic fluid release from smoke generation machine to
		concrete floor@CFA-1614; 3) 4/25/01, 3 cups motor oil release to concrete while being added to vehicle @CFA-1617 fuelling station; 4) 4/26/01, approx. 1 qt. hydraulic fluid release to pavemen @STF D&D site; 5) 5/7/01, 2 cups hydraulic fluid leaked to concrete from lawn mower north sid of CFA-602; 6) 5/15/01, 1 pint hyd.fluid leaked to soil from forklift #75231 @Landfill; 7) 5/15/01, 1 cup hyd. fluid release to pavement from hydraulic cylinder behind CFA-696; 8) 5/22/01, 2 to 3 gal. motor oil spilled to asphall@CFA-696 diesel fueling island; 9) 5/23/01, 2 pints diesel fuel released to soil from tank refilling @CPP-698 WAG-3 project outside fence; current WDDF on file.
ShepherdL	04-Jun-2001 02:21 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	18-Apr-2001 02:46 PM	Update #19: Unlock for Review & Approval for Landfill Disposal; approx. 20 trash bags of Petroleum contaminated soil/gravel/rocks placed in 2' X 4' X 8' box from yards near CFA-674.
ShepherdL	18-Apr-2001 02:43 PM	SHEPHERDL, wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	11-Apr-2001 11:11 AM	Update #18: Unlock for Review & Approval for Landfill Disposal; 4/5/01 spill cleanup of approx. pint hydraulic fluid to soil from Heister forklift at the CFA Landfill; Existing WDDF in file; SNT's Spill Summary Report attached to file.
ShepherdL	11-Apr-2001 11:09 AM	SHEPHERDL, wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	22-Mar-2001 04:31 PM	Continuation Update #17; Review & Approval for Landfill Disposal; Spill Cleanup from: 11) 8/16/00, 1 pint gear oil from "Jig Bore" milling machine release to soil @CFA-674.
ShepherdL	22-Mar-2001 04:28 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	22-Mar-2001 02:48 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, wgs. Call Point-7, Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	22-Mar-2001 02:44 PM	Update #17: Unlock for Review & Approval for Landfill disposal; several trash bags of PCM placed in a couple of drums from numerous spill cleanups from: 1) 1/9/01, 1 pint hydraulic fluid
		release from bucket truck adjacent to CFA-888, 2) 11/3/700, 1 gal. dieset fuel release from fuel truck dispenser to soil near CFA landfill; 3) 11/29/00, 1 gal. diesel fuel release to asphalt from small portable heater @CFA-617; 4) 11/14/70, 12 oz. diesel fuel spill to asphalt from refueling equipment outside TRA fence:5) 11/11/20, 1 gal. diesel fuel spill to asphalt from refueling efforts to a generator @CFA-609; 6) 11/6/00, 1/2 gal. water soluble cutting oil release from drill press t asphalt @CFA-664; 7) 9/6/100, <1 qt. motor oil leak to soil from forklift @ CFA-674; 8) 8/21/00, cup motor oil release to soil from equipment in excess yard @CFA-674; 9) 8/18/700, 10 oz. diese fuel release to asphalt from generator outside CFA-681; 10) 8/21/00, 1 cup diesel fuel spill to soil behind CFA-696;
ShepherdL	22-Mar-2001 01:54 PM	SHEPHERDL, wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	06-Mar-2001 03:25 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, wgs. Call Point-7. Authorized on Generating Unit (CFA):
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	06-Mar-2001 03:22 PM	Update #16: Unlock for Review & Approval of bag of PCM from 03/5/01, approx.1 quart Hydraulic Fluid Spill cleanup @CFA Landfill from Sunroc Construction Co. dump truck; change P2/Waste Min: Pan reference, current WPDF on file.

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

Profile Change	s i nacory.	
User Name	Date	Explanation
ShepherdL	06-Mar-2001 03:12 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	19-Dec-2000 08:10 AM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL: wgs. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
shepherdl	19-Dec-2000 08:03 AM	Update #15: Unlock for Review & Approval of 1 X 55 gal. drum of PCM from Diesel & Hydraulic spill cleanups @ ARA/WAG5 activities;consists of (1) 6/29/00 2 pints Hyd.fluid leak from
		 carretequip.#75641),(2) 7/11/00 one cup Hyd.Fluid leak from backhoe,(3) 11/2/00 1/2 to one— gal. diesel fuel leak from generator. Change Generator and Technical contacts and current, vali charge number.
ShepherdL	19-Dec-2000 07:55 AM	SHEPHERDL. wgs. Cail Point-4. Authorized on Generating Unit (CFA).
ShepherdL	25-Sep-2000 04;12 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, wgs. Call Point-7: Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	25-Sep-2000 04:12 PM	Unlock for Update #14: Review & Approve 1X55 gal. drum PCS for landfil disposal; 8/24/00 cleanup from approx 1 qt. hydraulic fluid release from track-hoe @IET area @TAN & 8/31/00
		 deanup from approx. 1 pint hydraulic floid from an elbow fitting from Caterpiliar Tractor @ IET area @TAN.
ShepherdL	25-Sep-2000 04:06 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	21-Aug-2000 02:41 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, wgs. Call Point-7. Authorized on Generating Unit (*CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	21-Aug-2000 02:41 PM	Unlock for Continuation of Update #13:Review & Approve PCS for tandfill disposat: 8) 7/26/00 cleanup (1/2 lb.paper towels in bag) one to two tablespoons of mineral oil(<50 ppm PCB's) from
		overfilled transformer in CPA-624, 9) one bag PPE, Sampling equipment/ debris from sampling CFA-696(Big Shop) stockpiled PCS (2.2 cu.yd. prior to landfarm treatment)
ShepherdL	21-Aug-2000 02:32 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	21-Aug-2000 02;20 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL. wgs. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

Profile Chang	e History:	
User Name	Date	Explanation
ShepherdL	21-Aug-2000 02:19 PM	Unlock for Update #13: Review & Approve several bags PCS from CFA spill cleanups for land disposal rather than Landfarm Treatment due to presence of absorbants: 1) 3/08/00 cleanup(1)
		tos in 2 bags) of some pint dieset splift on aspirati behind CFA-822 - 2) 3/27/60 clearup (1/2 lb in bag) of < two cups hydraulic fluid release from Amkus tool to asphalt; 3) 4/18/00 cleanup (25 pigs/absorbants in bag) of < one gallon mineral oil (<50 ppm PCB's) splifled inside CFA-667; 4) 5/02/00 cleanup (5 lb. vermiculite in bag) of < one cup mineral oil (4-11 ppm PCB's) from drum leak in bed of pickup & floor of CFA-637; 5) 5/11/00 cleanup (5 lb. in bag) of approx. two quarts motor oil lost to soil from a portable generator on west side of CFA-888; 6) 5/21/00 cleanup (3 lb. in bag) of diesel from faulty nozzle on fuel delivery truck on south side of CFA-660; 7) 6/26/00 cleanup (1/2 lb. absorbant in bag) of approx. 1 pint of non-detergent 30 wt. motor oil discharged to soil near CFA-1611.
ShepherdL	21-Aug-2000 01:33 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	16-Aug-2000 11:00 AM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, wgs. Call Point-7, Authorized on Generating Unit (CFA),
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	16-Aug-2000 11:00 AM	Unlock for Update #12.Review & Approve 2 ea. 4'X4'X8' boxes and 85 gal. drum of PCS for landfill disposal rather than Landfarm Treatment due to containing absorbants and plastic. Contains the following: Hydraulic floid, motor oil, & pump oil spill cleanups from D&D's Security
		Training Facility (STF): 1) 7/17/00 two gal. hydraulic fluid leak to concrete from back hoe line breakage; 2) 6/26/00 one-half gal. hydraulic fluid leak to concrete from trackhoe sprung fitting on hyd.line; 3) 5/22/00 two gal. hydraulic fluid leak to soil from trackhoe line breakage; 4) 5/8/00 one pint lube oil leak to soil from previously drained motor being moved to staging area; 5) 4/13/00 one pint pump motor oil leak to soil & concrete pad from nipple failure on pump motor.
ShepherdL	16-Aug-2000 10:19 AM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	12-Jun-2000 03:56 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL: wgs. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	12-Jun-2000 03:56 PM	Unlock for Update #11: Review & Approve 1 drum of diesel & Hydraulic fluid spill cleanups containing soil/absorbants for landfill disposal from the following spills at IET: 1) 5/15/00 one ga
٠		 diesel leak from fuel fine on generation, 2) 5/22/200 1/2 gt. hyd.fluid retrasse from loose frose on- track hoe; 3) 5/25/00 1/2 gal. diesel release from fuel hose nozzle on fuel delivery truck fell ou 4) 5/25/00 1/2 pint hyd. fluid release from pin hole in track hoe line.
ShepherdL	12-Jun-2000 03:45 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	31-May-2000 02:52 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL: wgs. Call Point-7: Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	31-May-2000 02:52 PM	Unlock for Update #10 Landfill disposal approval of approx. 1 cu.yd. hydraulic fluid contaminate soil/absorbants from 5/31/00 approx.5 gal release from 0-ring seal blown on a trackhoe at the
ShepherdL	31-May-2000 02:47 PM	Security Training Facility. SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System



В.

Integrated Waste Tracking System Material and Waste Characterization Profile INFORMATION ONLY



1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

User Name	Date	Explanation
		BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
ShepherdL	09-May-2000 03:43 PM	SHEPHERDL, wgs. Call Point-7. Authorized on Generating Unit (CFA),
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	09-May-2000 03:43 PM	Unlock for Modification of Update #9 landfill disposal approval of PCM cleanups not suitable landfarm treatment: an additional approx. 3 c.y.ds. hydraulic fluid contaminated soli/absorbar from 5/9/00 second release from the same piece of equipment at the same hocation.
ShepherdL	09-May-2000 03:18 PM	SHEPHERDL wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	09-May-2000 02:05 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
 -		SHEPHERDL: wgs. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	09-May-2000 02:04 PM	Unlock for Update #9 landfill disposal approval of PCM cleanups not suitable for landfarm treatment: approximately 3 cu.yds. hydraulic fluid contaminated scil/absorbants from 5/9/00 f to ten yai, release from hose coupling breakage on Case 310-9060 Excavator (Equip.#75670
ShepherdL	09-May-2000 01:56 PM	the STF D&D site. SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	16-Mar-2000 04:51 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, wgs. Call Point-7. Authorized on Generating Unit (*CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	16-Mar-2000 04:51 PM	Unlock for Update #8 landfill disposal approval of PCM cleanups not suitable for landfarm treatment: 1)6 drums fuel oil contam.soil, PPE, sampling materials, lexen tubes from WAG 1 Fuel Leak Site WRRTF-13 near TAN(TSF-08 Charlyss Lee for Doug Kuhns) , 2/8 drums dies
		fuel contarrs, soil, rocks, wood chips, &Non-ACM insulation from STF fuel tank area(Jeff Allen) 3)2 drums hydraulic fluid, tube oil & grease contaminated soil, rocks, wood chips, & Non-ACM insulation from spill cleanups from Heavy Equipment at STF (Jeff Allen) 4) Approx. 4 drums hydraulic fluid contam, soil, rocks, wood chips, &Non-ACM insulation from spill cleanups fron Heavy Equipment at CFA's Sewage Treatment Plant area.(Randy Drage); 5)1 plastic trash b <5 gal.#2 fuel oil contam, kitty litter from maintenance on malfuctioning furnace in PER619(Ji Clark)
ShepherdL	16-Mar-2000 04:42 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	14-Mar-2000 10:52 AM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL: wgs: Call Point-7: Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	14-Mar-2000 10:51 AM	Unlock for Update #7 landfill disposal approval of PCM cleanups not suitable for Landfarm Treatment: I plastic trash bag of corn cob absorbants contaminated with approx.<1 gal. of Ingersoff-Rand Air compressor oit, 31:205, from rentat unit placed in PER-305, The oit
		contaminated com cobs were placed in a plastic trash bag and leak area was cleaned with non-haz. Compublend il degreaser & residues placed in bag with com cobs.
ShepherdL	14-Mar-2000 10:35 AM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System



В.

Integrated Waste Tracking System Material and Waste Characterization Profile INFORMATION ONLY 1980N : PCM- Unsuitable for Landfarm (prev WIO# 3065)



User Name	Date	Explanation
ShepherdL	19-Jan-2000 12:15 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
· · · · · · · · · · · · · · · · · · ·	** **	SHEPHERDL. wgs. Call Point-7, Authorized on Generating Unit (CFA):
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	19-Jan-2000 12:15 PM	Unlock for Update#6 landfill disposal approval of PCM spill cleanups not suitable for Landfarm Treatment: 1) 1 X 55 gat, drum and 3 Large plastic bags containing gravel and absorbants fro a 11/23/99 and 12/9/99 hydraulic fluid spill cleanups from a subcontractors driffling rig project
		near RVMC; 2) 1 X 55 gal. drum contaminated soil, gravel, and absorbants from diesel and hydraulic fluid spill cleanups from heavy equipment over a period of several months at the ARI D&D location(Rod Nelson)
ShepherdL	19-Jan-2000 12:04 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	08-Dec-1999 11:26 AM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL. wgs. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	08-Dec-1999 11:26 AM	Continuation of Update#5 approvals: 5) is currently stored at D&D's CFA storage area.(Don Hurley/James Clayton); 6) 2 poly bags(approx. 10-15 gals.) of diesel fuel contaminated media from a 11/11/99 spill cleanup of a fuel funck (#E7/1716) parked on an incline near MWSF-PER 613.(Shawn Tigue); 7) 1 poly bag(approx. 5-8 gals.) of #2 Diesel Fuel Oil/vermiculite from a 3/9/99 spill cleanup during maintenance related work at MWSF PER 613, room 106.(Shawn Tigue); 8) 3X5 gal.cans of diesel fuel oil contaminated media from spill cleanups near a 300 g fuel oil tank, PER-711, at WERF.(Al Millhouse/Bob Miles); 9) 1 poly bag(approx. 10 gals.) of corn cob absorbants/gravel contaminated with new 10W oil from a 11/9/99 spill cleanup at WROC, PER-612.(Shawn Parkinson)
ShepherdL	08-Dec-1999 11:17 AM	SHEPHERDL, wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	08-Dec-1999 11:12 AM	Unlock for Update#5 landill disposal approval of PCM spill cleanups not suitable for Landfarm Treatment: 1) 4 drums solidified compressor oil from the IET D&D project at TAN.(Harold
		Thorne), 2) 3X55 gal.drums at IET D&D site at TAN containing numerous poly begs of motor oil/hydraulic fluid spill cleanups from heavy equipment over a period of several months (Harold Thorne); 3) small poly bag of absorbants/gravel/soil from a 11/15/99 hydraulic fluid spill cleant @ CFA-674 Excess Facility West Yard from a FIAT ALLICE scraper hydraulic hose leak (Rick Driever); 4) 1X55 gal.drum (1/2 full) floor dry/flabric sorbants contaminated with motor oil/hydraulic fluid from D&D heavy equipment at the C&S jobsite at TRA. Currently the drum is stored in a D&D CONNEX box at the TRA-660 jobsite (Donna Hurley): 5) small poly bag of hydraulic fluid contaminated media from a Case 690 Trackhoe spill cleanup at the C&S buildin dismantling at RWMC earlier this year. The poly bag is currently stored at
ShepherdL	08-Dec-1999 10:53 AM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	17-Nov-1999 11:19 AM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL. wgs. Call Point-7. Authorized on Generating Unit (C
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System






1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

:
:

User Name	Date	Explanation
ShepherdL	17-Nov-1999 11:18 AM	Unlock for Update #4 landfill Disposal approval of PCM spill cleanups not suitable for Landfarm Treatment: 1) 1 X 55 gal. drum containing soil gravel, and absorbants from a 3/2/98 hydraulic
		uit spill cleanap from the Caterpillar D8 dozer, Equip #73712, outside and on the west side of STF-601; 2) 1 X 55 gal, drum of contaminated soil from a 4/28/99 spill cleanup of diesel fuel from an abandoned underground line at the CFA Security Training Facility; and 3) several cubic feet of soil/gravel/wood chips from a 11/17/99 transmission fluid spill cleanup from a Tractor/Trailer rig, Equip # 71799, while being operated at the CFA Landfill & subsequent roadways at the Landfill.
ShepherdL	17-Nov-1999 11:12 AM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	15-Nov-1999 04:54 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL: wgs. Call Point-7. Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	15-Nov-1999 04:54 PM	Unlock for Update#3 Landfill Disposal approval of PCM spill cleanups not suitable for Landfarm Treatment: 1) 7 small bags placed in a 55 gal, drum containing soil, gravel, and absorbants from a 10/25/99 unleaded gasoline spill cleanup at the CFA Fueling Island, 2) approximately 5 gal-of contaminated soil and absorbants from a 10/21/99 spill cleanup of motor oil outside the fence at the North Site @ RWMC; and 3) a 55 gal, drum of gravel and terri wipes from a hydraulic fluid spill cleanup on a drill rig outside the fence @ RWMC. Also placed note in Comment Section; "Waste Stream amy also consist of unleaded gasoline small spill cleanups involving absorbants".
ShepherdL	15-Nov-1999 04:47 PM	SHEPHERDL, wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	15-Nov-1999 04:45 PM	BEGIN VALIDATION FOR MATERIAL PROFILE ANNUAL REVIEW
		SHEPHERDL, wys. Call Point-7, Authorized on Generating Unit (CFA).
		COMPOSITION VALIDATION PASSED
		OVERALL VALIDATION PASSED
ShepherdL	15-Nov-1999 04:44 PM	С
ShepherdL	15-Nov-1999 04:30 PM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	20-Oct-1999 10:10 AM	SHEPHERDL. wgs. Call Point-7. Authorized on Generating Unit (CFA).
ShepherdL	20-Oct-1999 10:09 AM	Unlock for Update #2 Landfill disposal approval of PCM spill cleanups not suitable for Landfarm Treatment:1)Two small trash bags located in CFA-637 containing absorbants from a 10/13/99 spill cleanup from a dieset fuel oil fitting leak on boiler in CFA-808. 2) A 55 gathfrom containing
		gravel and rags/pillows from a hydraulic fluid spill cleanup at the OMRE facility.
ShepherdL	20-Oct-1999 10:04 AM	SHEPHERDL. wgs. Call Point-4. Authorized on Generating Unit (CFA).
ShepherdL	15-Sep-1999 03:16 PM	SHEPHERDL. wgs. Call Point-7. Authorized on Generating Unit (CFA). Overall Authorization Passed.
ShepherdL	15-Sep-1999 03:15 PM	Unlock for Update#1 approval for landfill disposal of following PCM spill cleanups that are not landfarm titmt. candidates:1)small trash bag located in CFA-637 contain, sampling equipment from sampling container used uil*CFA 637-unknown(used uil*file is in care of Sydney Flood, 2)*
_ _		55 gal. drum@Harold Thorne's D&D site contain.numerous 6 mil poly bags of motor oi&Hydraulic fluid spill cleanups from heavy equipment over a period of several months; 3) small trash bag located in CFA-637 containing an 8/31/99 dieset spill cleanup in front of CFA-615 w/absorbants.
ShepherdL	15-Sep-1999 03:09 PM	SHEPHERDL, wgs. Call Point-4. Authorized on Generating Unit (CFA). Overall Authorization Passed.

25-Oct-2002

Report[MaterialProfile], Integrated Waste Tracking System





1980N : PCM- Unsuitable for Landfarm (prev WID# 3066)

User Name	Date	Explanation
ShepherdL	17-Aug-1999 02:21 PM	SHEPHERDL. wgs. Call Point-7. Authorized on Generating Unit (CFA). Overall Authorization Passed.
ShepherdL	17-Aug-1999 02:21 PM	Unlock for approval: Approving 2 drums of < 1/3 cu.yd. from spill cleanups for landfill disposal rather than landfarm treatment due to presence of rags/towels/absorbants which are not
		conductive to methods employed at the landfarm trunt, area: These spitts occurred from hydraulic fluid leaks and motor oil leaks from front-end loader, trackhoe, and truck on the INEEL Road Rehabilitation Project.
ShepherdL	17-Aug-1999 02:17 PM	SHEPHERDL wgs. Call Point-4. Authorized on Generating Unit (CFA). Overall Authorization Passed.
roher	16-Aug-1999 08:30 AM	ROHER. wgs. Call Point-6. Authorized on Generating Unit (CFA), Overall Authorization Passed.
roher	16-Aug-1999 08:26 AM	review for WGS reviewer signature
roher	16-Aug-1999 08:26 AM	ROHER. wgs. Call Point-4. Authorized on Generating Unit (CFA). Overall Authorization Passed.
unterk	04-Aug-1999 03:03 PM	To change the petroleum products discription in the composition page
unterk	04-Aug-1999 03:01 PM	UNTERK. wgs. Call Point-4. Authorized on Generating Unit (CFA). Overall Authorization Passed.
unterk	04-Aug-1999 01:42 PM	UNTERK. wgs. Call Point-5. Authorized on Generating Unit (CFA). Overall Authorization Passed

- End of Report

Attachment H (Appendix A)

Vendor Data Status Report and Schedule

http://thomar2.inel.gov/pls/vds/vdcs_reports.vdcs_status_report?swp_identifiet=21891

Vendor Data Schedule

WAGONER DEBORAH WIGGINS Manufacturers Data Report W. Shop Drawings W. John Drawin	Project Title	WAG 4 - CFA-08 STP DRAINFIELD COVER	ELD COVER		Project No. S-00007664
dinator Address Holinator Address K. Manufacturers Data Report H. Oshop Drawings K. Manufacturers Data Report H. Oshop Drawings H. Hardware Scheduie W. Shop Drawings H. Hardware Scheduie W. Special Processes O. Procedurelinstructions P. Pump Head Curves O. Procedurelinstructions P. Pump Head Curves O. Procedurelinstructions P. Pump Head Curves O. Poperational C Test Reports A. ULFM Listing A. M. Certificate of Conformance A. Weld Records A. Certificate of Conformance A. Weld Records A. Design Verification	System Engineer/ Project Manager	WAGONER DEBORAH WIGGIN		R-02	Rev: 0
K. Manufacturers Data Report W. Survey Records M. Parts List M. Recommended Spares M. Special Processes M. Recommended Spares M. Special Processes M. Recommended Spares M. Special Processes M. Recommended Spares M. Certification M. Sample(Color, Texture, etc.) M. Wring Diagrams M. Design Verification M. Design Verifica	₩	nator Address	POOLE M AN	INETTE, TSB-1WI404, MS: 3915	
K. Manufacturers Data Report L. O&M Manual M. Parts List M. Test Procedure S. Special Processes A. Membrandard Spares A. Medicalion A. Recommended Spares A. ULFM Listing A. Necaminate A. Servicion A. Recommended Spares A. Wring Diagrams S. RSMI & Maintenance Log A. Wring Diagrams A. Design Verification	Vendor Data Codes				
BFA - Before Final Acceptance PTP - Prior to Purchase PTC - Prior to Construction Start BFR - Before Abrication Release PS - Prior to Shipment PTI - Prior to Installation PTI - Prior to United PTI - Prior to Welding PTI - Prior to Delivery on site	A. As-Bult Drawings B. Assembly Drawings C. Attendance Record D. Blasting Plan E. Catalog Dala E. Chem & Physical Analysis G. Concrete Mix Design G. Concrete Mix Design H. Control System Diagram I. Design Calculations J. Installation	K. Manufacturers Data Report L. O&M Manual M. Parts List M. Piping Drawing O. Procedurelinstructions P. Purmy Head Curves P. Personnel Qualifications R. Red line Drawings S. RSM & Maintenance Log T. Sample(Color, Texture, etc.)	sting eal	lule Inspection/Test Plan Spares st mormance sposal or Destruction ion	AC Design Qualification Testing AP. Traceability Procedure AR, Weld Procedure AR, Weld Procedure Qualification AS. Welder Performance Personnel AI. Worlder Performance Personnel AI. Non-Destructive Examination AI. Unspector Certifications AV. Limited Sheff Life/Operational Data AW. Special Packaging, Shipping, and Rigging Procedure AX. Certificate of Materials to ASME Code Code AY. Chemical Inventory AZ. Other
BFA - Before Final Acceptance PTP - Prior to Purchase PTC - Prior to Construction Start BFR - Before Fabrication Release PS - Prior to Shipment PTI - Prior to Installation PTS - Prior to Delivery on site	When to Submit				
	AC - As Completed AT - After Test BC - Before Contract Awarded	BFA - Before Final Acceptance BFR - Before Fabrication Release ROS - Removed Off-Site PDS - Prior to Delivery on site		PTC - Prior to Construction Start PTI - Prior to Instaliation PTW - Prior to Welding	TS - Time of Shipment WP - With Proposal

10/23/02 2:41 PM

O
_
_
=
•
4
=
_
u
മ
V 1
_
2
=
.53
Ä
പ
_
_
ᆽ
~
71
=
43
-
•

1						
Ę .	Clause/Article or Drawing/Specification Reference	Description	Vendor Data Code	Extra Copies Reguired	When to Submit	Approval Code
	01051	PROFESSIONAL LAND SURVEYOR CERTIFICATION	Q. Personnel Qualifications	0	PTC - Prior to Construction Start	2. Information Only
	01051	COPY OF SURVEYOR'S LOGBOOK	AY. Chemical Inventory	0	AC - As Completed	2. Information Only
	01051	TOPOGRAPHICAL SURVEYS	V. Survey Records	0	AC - As Completed	1. Approval Required
	01300	REDLINE DRAWINGS (CONSTRUCTION DRAWINGS)	R. Red_line Drawings	0	BFA - Before Final Acceptance	2. Information Only
1	02200	CONSTRUCTION WORK PLAN	O. Procedure/Instructions	0	PTC - Prior to Construction Start	1. Approval Required
	02200	SIEVE TEST REPORTS (FOR OFF-SITE MATERIALS)	Z. Test Reports	0	PDS - Prior to Delivery on site	1. Approval Required
	prd 2101 & 4002	CREMICAL INVENTORY LIST - FORM 432,21 (QUARTERLY REPORT)	AY. Chemical Inventory	0	AC - As Completed	2. Information Only
	PRD 2101 & 4002	CHEMICAL INVENTORY LIST - FORM 432.21 (FINAL REPORT)	AY. Chemical Inventory	0_	ROS - Removed Off-Site	2. Information Only
	PRD 2101 & 4002	CHEMICAL INVENTORY LIST - FORM 432.21, INTIAL AND RE-SUBMITTALS/WITH SUPPORT MSDS	AE. MSDS	0	PDS - Prior to Delivery on site	1. Approval Required
	SC-3	LIST OF DIESEL AND GASOLINE FUELED ENGINES	AY. Chemical Inventory	0	PTC - Prior to Construction Start	1. Approval Required

Instructions: 1. Refer to subcontract documents for instructions on submittals,
2. Electronic submittals in their of paper documents are acceptable and encouraged.
3. The normal number of copies required is ONE. If more are required, the number will be shown here.
4. THE INEEL WILL SCAN ALL SUBMITTED VENDOR DATA INTO A SYSTEM THAT IS ACCESSIBLE TO ALL INEEL EMPLOYEES UNLESS THE SUPPLIER/SUBCONTRACTOR IDENTIFIES SUBMITTED INFORMATION AS PROPRIETARY.

10/23/02 2:41 PM